

2018 Toyota CAMRY



(data:image;base64,/9j/4AAQSkZJRgABAQEAAAAAAAAAD/2wBDAAUDBAQEAwUEBAQFBQUGBwIBwCHBw8LCwkMEQ8SEhEPERETFhw)



(data:image;base64,/9j/4AAQSkZJRgABAQEAAAAD/2wBDAAUDBAQEAwUEBAQFBQUGBwwIBwchBw8LCwkMEQ8SEhEPERTFhw)



(data:image;base64,/9j/4AAQSkZJRgABAQEAAAAAAAAAD/2wBDAAUDBAQEAwUEBAQFBQUGBwwIBwcHBw8LCwkMEQ8SEhEPERETfhw)



(data:image;base64,/9j/4AAQSkZJRgABAQEAAAAD/2wBDAAUDBAQEAwUEBAQFBQUGBwwIBwcHBw8LCwkMEQ8SEhEPERETfhw)



(data:image;base64,/9j/4AAQSkZJRgABAQEAAAAAAAAAD/2wBDAAUDBAQEAwUEBAQFBQUGBwwIBwchBw8LCwkMEQ8SEhEPERETfhw)



(data:image;base64,/9j/4AAQSkZJRgABAQEAAAAAAAAAD/2wBDAAUDBAQEAwUEBAQFBQUGBwwIBwchBw8LCwkMEQ8SEhEPERETfhw)



(data:image;base64,/9j/4AAQSkZJRgABAQEAAAAD/2wBDAAUDBAQEAWUEBAQFBQUGBwwIBwchBw8LCwkMEQ8SEhEPERTFhw)



(data:image;base64,/9j/4AAQSkZJRgABAQEAAAAD/2wBDAAUDBAQEAwUEBAQFBQUGBwwIBwcHBw8LCwkMEQ8SEhEPERFFhw)

MFD. BY: TOYOTA MOTOR MANUFACTURING,
KENTUCKY, INC. 08/17

GVWR 4475LB GAWR FR 2620LB RR 2420LB
THIS VEHICLE CONFORMS TO ALL APPLICABLE
FEDERAL MOTOR VEHICLE SAFETY, BUMPER AND
THEFT PREVENTION STANDARDS IN EFFECT ON
THE DATE OF MANUFACTURE SHOWN ABOVE.

4T1B11HK7JU505475 PASS. CAR



C/TR:1H1/EA20 AXVA70L-CEZSBA
A/TM:-02A/UB80E MADE IN U.S.A. 53627



(data:image;base64,/9j/4AAQSkZJRgABAQEAAAAD/2wBDAAUDBAQEAWUEBAQFBQUGBwwIBwCHBw8LCwkMEQ8SEhEPERETfhw)
*click on an image to enlarge

Vehicle Information

| | |
|----------------------|--|
| VIN: | 4T1B11HK7JU505475 |
| Vehicle: | 2018 Toyota CAMRY |
| Location: | CARTERET , NJ 07008, USA |
| Auction End Date: | Monday, June 17, 2019 06:00 AM Pacific Standard Time |
| Actual Cash Value: | \$18,314 USD |
| Odometer: | 24,020 mi - ACTUAL |
| Damage Type: | RIGHT FRONT; LEFT REAR |
| Loss Type: | COLLISION |
| Exterior / Interior: | GRAY / BLACK |
| Body Style: | SEDAN 4 DOOR |
| Fuel Type: | |
| Cylinders: | |
| Manufactured In: | |
| Keys: | yes |
| Seller: | Plymouth Rock Assurance Corp |
| StartCode: | |
| SaleDocTitle: | |
| Model: | |
| Engine: | |
| RestraintSystem: | |
| Transmission: | |
| DriveLineType: | |
| Damage: | |
| Airbags: | |
| EstimatedRepairCost: | |